





CUSTOMER SUPPLY
FIELD WIRING

DWG. NO HQ - 95200A



** TERMINAL BLOCK **



** NOTE **

- OLS : OPEN LIMIT SWITCH
- CLS : CLOSE LIMIT SWITCH
- CTS : OPEN TORQUE LIMIT SWITCH
- O/C : OPEN/CLOSE POWER RELAY(DC 24V)
- RL : RED LAMP FOR OPEN
- GL : GREEN LAMP FOR CLOSE
- YL : YELLOW LAMP FOR FAULT
- RY1 : FAULT MONITOR RELAY
- RY2 : FAULT RELAY
- RY3 : FAULT RELAY
- RY4 : RUNNING RELAY
- ◎ : MARKS FOR TERMINAL
- ◎ 25 : 26 : SETTING TERMINAL

** LIMIT SWITCH CONTACT POSITIONS **

CON-TACT	VALVE OPENING (%)
100	100
0	0
2-3	2-3
1-3	1-3
2-3	2-3
1-3	1-3
2-3	2-3
1-3	1-3

PROJ.	SYM	ECN NO	CHANGES	DATE	SIGN	APPR.
DRAW	P.S. KIM	SCALE 1/1	ISSU. DEPT. HADR	PART NAME	SCHEMATIC WIRING DIAGRAM	
DESIGN	S.I. CHOI	DIM. mm	DATE 2004.06.10	LCU-C		
CHECK	EIM CONTROLS			DWG. NO	HQ - 95200A	
APPR.				1 OF 1 SHEET	DWG. SIZE A4	