





CUSTOMER SUPPLY
FIELD WIRING



POWER SOURCE
3φ 220V
3φ 380V
3φ 440V
3φ 460V
3φ 480V
60HZ

** TERMINAL BLOCK **



** NOTE **
OLS : OPEN LIMIT SWITCH
CLS : CLOSE LIMIT SWITCH
OTS : OPEN TORQUE LIMIT SWITCH
O/C : OPEN/CLOSE POWER RELAY (DC 24V)
RL : RED LAMP FOR OPEN
GL : GREEN LAMP FOR CLOSE
YL : YELLOW LAMP FOR FAULT
RYL : YELLOW MONITOR RELAY
RY3 : FAULT RELAY
RTZ/RT4 : RUNNING RELAY
● : MARKS FOR TERMINAL
● 25 : 27 : SETTING TERMINAL

** LIMIT SWITCH CONTACT POSITIONS **		
CON-TACT	VALVE OPENING (%)	
ROTOR	0	100
OPEN	2-3	
(OLS)	1-3	
CLOSE	2-3	
(CLS)	1-3	

--- : CONTACT ON
---- : CONTACT OFF

PROJ.	SYM	ECN NO	CHANGES	DATE	SIGN	APPR.
DRAW	P.S. KIM	SCALE 1/1	ISSU. DEPT. HADR	PART NAME SCHEMATIC WIRING DIAGRAM		
DESIGN	C S I	DIM. mm	DATE 2004.03.19	ICU-LCU-C(INTEGRAL+PCU)		
CHECK	EIM CONTROLS			DWG. NO HQ - 95500A		
APPR.				1 OF 1 SHEET	DWG. SIZE A4	

DWG. NO HQ - 95500A